

Mr. Sam Chummar Remedial Project Manager USEPA Region 5 Superfund Division Remedial Response Section #1 77 W. Jackson Blvd. (SR-6J) Chicago, IL 60604 ARCADIS of New York, Inc. 6723 Towpath Road Syracuse New York 13214-0066 Tel 315.446.9120 Fax 315.449.0017 www.arcadis-us.com

INDUSTRIAL

Subject

Georgia-Pacific Corporation Time Critical Removal Action Monthly Progress Report #11

Dear Mr. Chummar:

Attached is the eleventh monthly progress report for the Time Critical Removal Action (TCRA) at the Georgia-Pacific Corporation (Georgia-Pacific) Kalamazoo Mill Property and the former Hawthorne Mill Property (collectively referred to as the Mill Properties). The Mill Properties are associated with the Allied Paper, Inc./Portage Creek/Kalamazoo River Superfund Site. This report has been prepared pursuant to the Administrative Settlement Agreement and Order on Consent (AOC), Docket No. V-W-'07-C-858, and covers activities from September 15, 2007 through October 12, 2007.

Sincerely,

ARCADIS of New York, Inc.

Date:

October 22, 2007

Contact:

Patrick N. McGuire

Phone:

315.671.9233

Email

Pat.McGuire@arcadisus.com

Our ref:

B0066105.001

Patrick N. McGuire

Associate

PNM/dmn Enclosures

Mr. Sam Chummar October 22, 2007



#### Copies:

Eileen L. Fury, Esq., USEPA - Region 5
Mellonie S. Fleming, Esq., Georgia-Pacific Corporation
L. Chase Fortenberry, P.G., Georgia-Pacific Corporation
Paul T. Bucholtz, MDEQ-RRD-Superfund
Daria W. Devantier, MDEQ-RRD-Superfund
Matthew Bowman, ARCADIS BBLES
Christie Sobol, ARCADIS BBL



#### I. Significant Developments

#### **Actions Performed**

 Prepared the Inspection Report for the August 24, 2007 inspection of erosion and sedimentation controls (attached).

#### **Analytical Data**

No new analytical data was obtained during this reporting period.

#### II. Developments Anticipated

#### Schedule of Actions to be Performed

 Comments on the Draft Final Report provided by the USEPA will be addressed and the Final Report will be finalized and submitted to the USEPA.

#### **Anticipated Problems**

None.

### **Planned Resolutions of Past or Anticipated Problems**

None.

# Georgia-Pacific Corporation Time Critical Removal Action Refuse Area at the Kalamazoo Property and Oxbow Area at the Former Hawthorne Mill Property Post-Removal Inspection Form

Inspection Date: 8-24-07 Inspectors: STEVE TAPLY		Weather Conditions: SUNNY 75		
Time Arrived: \( \sum_{\ell} \) \( \sigma \)	O	(AM)/PM)	Time Departed: 10.41	(S(AM/PM)
A. Site Access Road				
• Erosion/\	Vashout/Settlement		1)/	
Sufficient	t Gravel			4
B. Site Security		·	10//	1
Access G	ates	L		
Fence Int	egrity	V		
• Signs		i e		
• Locks		<i>U</i> -		
C. A-Site Temporary	Cover System			
Bare Spo	ts	1.7		
Stressed	Vegetation	1-		
Cracks		L'		· · · · · · · · · · · · · · · · · · ·
Burrowin	g Animals	V	***	
• Erosion		· ·		
Settlement	nt	V		
Water Po	onding	V		
Protrudir	ig Objects	U		
Undesira	ble Growth	V		
Slope Mo	ovement	v		
D. Sheetnile Wall				

## Georgia-Pacific Corporation Time Critical Removal Action Refuse Area at the Kalamazoo Property and Oxbow Area at the Former Hawthorne Mill Property Post-Removal Inspection Form

<ul> <li>Erosion Subsidence or</li> </ul>		
Cracking of Soils Behind		
Wall		N/A
• Wall Joints		
		$\mathcal{N}/_{I+}$
Overall Wall Stability		N/A N/A
E D C		N/A
E. Refuse and Oxbow Areas Slope		
Protection System		
Bank Erosion		
Rip Rap Revetment		
Stressed Vegetation	V	
Bare Spots		
	V	
I. Overall Site Appearance	./	
		Capeut

Comments/Proposed Action Items:

### Georgia-Pacific Corporation Time Critical Removal Action

### Refuse Area at the Kalamazoo Property and Oxbow Area at the Former Hawthorne Mill Property Post-Removal Inspection Form

		rosi-kemovai inspe	ction Form	
-	8-24-07 Steve TAP	VIN	Weather Conditions: SUNNY EDO	
Time Arrived:	/1.00	(AM)PM)	Time Departed: <u>/ パリロ</u>	(AM/PM)
A. Site Acces				n, de Rojeje Al Majori Uras Parasi
	Action washoursement	""	A) /a	

Diff Color		
A. Site Access Road		
Erosion/Washout/Settlement	<u> </u>	
		10/4
Sufficient Gravel		
P. 64. 6		N/A N/A
B. Site Security		
Access Gates		
		N/A
Fence Integrity		
• Signs		NA
• Signs		
• Locks		
		ル/ <sub>4</sub>
C. A-Site Temporary Cover System		
Bare Spots		
Bare Spots	v	
Stressed Vegetation	<del></del>	
	L-	
<ul> <li>Cracks</li> </ul>	V	
Burrowing Animals		
Bullowing Amiliais	4-	
• Erosion		
	1	
Settlement	L-	
Water Ponding	-	
water rending	6	
Protruding Objects	4-	
	U	
Undesirable Growth	L	
Slope Movement		
D. Sheetpile Wall		427.
		10/4

## Georgia-Pacific Corporation Time Critical Removal Action Refuse Area at the Kalamazoo Property and Oxbow Area at the Former Hawthorne Mill Property <u>Post-Removal Inspection Form</u>

Erosion Subsidence or		
Cracking of Soils Behind Wall		#1/a
Wall Joints		10//-
		N/A
Overall Wall Stability		7 - 1 /4
		NA
Refuse and Oxbow Areas Slope Protection System		
Bank Erosion	1./	
Rip Rap Revetment		
Stressed Vegetation	1/	
Bare Spots		
Overall Site Appearance		fully vegethred

Comments/Proposed Action Items: